



JOB DESCRIPTION

Job Title: Robotic welder Set up Operator

Job Code:

G3 Plant: Mosinee

FLSA Status: Non-exempt

Department: 50

Reports To: Production Manager

Principle Duties and Areas of Responsibility:

- ▶ Must be able to set up and run robotic welders at or above established quality and efficiency standards.
- ▶ Set up and run according to production schedule.
- ▶ Set up all jobs according to blueprint specifications and tolerances.
- ▶ Measure dimensions of finished work pieces to ensure conformance to specifications using calipers, height gages, templates, rulers, etc.
- ▶ Must be able to read blue print, distinguish / identify types and size and length and strength of welds.
- ▶ Safely and accurately operate machines to produce pieces to quality and efficiency standards, including repetitively lifting of hot parts to and from machines manually.
- ▶ Ability to read work orders to determine specifications, such as materials and proper sub-components to be used, dimensions and tolerances, proper labeling of parts, etc. and accurately complete all required functions to ensure only quality product is produced.
- ▶ Accurately document/record information in written and electronic form.
- ▶ Perform operator maintenance on machines per established schedules, (clean, lubricate, change wire liners, change gas tanks, wire tips, etc).
- ▶ Support achievement of company standards in safety, efficiency, quality, on-time production etc.
- ▶ Assist in rapid improvement projects to improve departmental metrics as required to maximize value and reduce costs along with continuous improvement of product and process quality in all areas.
- ▶ Other tasks as required.

Education:

Technical welding degree preferred or equivalent experience.

Skills and Abilities:

- ▶ Basic mechanical ability
- ▶ Must display good judgment, work well independently, and work well with others.
- ▶ Strong Quality work ethic is required.
- ▶ Must be self-motivated and able to work independently

Physical Requirements:



JOB DESCRIPTION

Reasonable accommodations may be made to enable individuals with disabilities to perform the essential functions. Use these codes to complete this section: "F" for frequently; "O" for occasionally; "N" for not at all.

Physical Activity

On the job the employee must:

- (F) Bend (N) Sit
 (F) Squat (F) Stand
 (O) Crawl (F) Walk
 (N) Climb (F) Push/Pull
 (O) Kneel
 (F) Handle objects (manual dexterity)
 (O) Reach above shoulder level
 (O) Use fine finger movements
 (F) Repetitive movement
 () Other _____

Must carry/lift loads of:

- (F) Light (up to 25lbs.)
 (F) Moderate (25-50lbs.)
 (F) Heavy (over 50lbs.)

Physical Ability:

- Vision: Good
 Color Vision: Normal
 Hearing: Normal
 Talking/Speech: Good

Physical Exposure

On the job the employee:

- (F) Is exposed to moderate or excessive (circle) noise
 (F) Is around moving machinery
 (F) Is exposed to marked changes in temperature and/or humidity
 (F) Is exposed to dust, fumes, gases, microwave, Other _____ (circle)
 (O) Drives motorized equipment
 (F) Works in confined quarters
 (N) Unprotected heights
 () Other _____

Acceptable Minimum

- Poor Blind
 Impaired
 Moderate Loss Deaf
 Fair Mute



JOB DESCRIPTION

APPROVALS:

(Insert Appropriate Title) Manager

Date

Human Resources Manager

Date

The above is intended to describe the general content of and requirements for the performance of this job. Employees may be required to perform other duties to meet the on-going needs of G3.
